

Sample ID	Location	Analysis	Result	MCL (EPA acceptable level)	Units
6031489-01	371 Walnut Street Kitchen Sink	Chlorine, Free	1.18	4.0	mg/L
		Total Coliform	0.00	0.0	MPN
		E. Coli	0.00	0.0	MPN
6031489-02	Royersford Fire Co Kitchen Sink	Chlorine, Free	1.14	4.0	mg/L
		Total Coliform	0.00	0.0	MPN
		E. Coli	0.00	0.0	MPN
6031489-03	Royersford Elem Conference Room Sink	Chlorine, Free	1.24	4.0	mg/L
		Total Coliform	0.00	0.0	MPN
		E. Coli	0.00	0.0	MPN
6031489-04	Sweet Ashley's Hand Sink	Chlorine, Free	1.36	4.0	mg/L
		Total Coliform	0.00	0.0	MPN
		E. Coli	0.00	0.0	MPN
6031489-05	Royersford Muni Garage Kitchen Sink	Chlorine, Free	1.40	4.0	mg/L
		Total Coliform	0.00	0.0	MPN
		E. Coli	0.00	0.0	MPN
6031489-06	Royersford Boro Hall Mens Room Sink	Chlorine, Free	1.28	4.0	mg/L
		Total Coliform	0.00	0.0	MPN
		E. Coli	0.00	0.0	MPN
6031490-01	371 Walnut Street	Copper	0.235	1.300	mg/L
		Lead	0.010	0.015	mg/L
6031490-02	Royersford Fire Co Kitchen Sink	Copper	0.147	1.300	mg/L
		Lead	0.002	0.015	mg/L
6031490-03	Royersford Elem Conference Room Sink	Copper	0.711	1.300	mg/L
		Lead	0.002	0.015	mg/L
6031490-04	Sweet Ashley's Hand Sink	Copper	0.047	1.300	mg/L
		Lead	0.007	0.015	mg/L
6031490-05	Royersford Muni Garage Kitchen Sink	Copper	0.383	1.300	mg/L
		Lead	<0.001	0.015	mg/L
6031490-06	Royersford Boro Hall Mens Room Sink	Copper	0.165	1.300	mg/L
		Lead	0.001	0.015	mg/L